

Yealink UK T40P/T41P/T42G – V80 Change log.

Release date	Model	Firmware Version		Changelog
		Form	To	
11/6/2015	T40	Yealink neutral version	54.80.23.1	Transplant customized configurations for the UK.
11/6/2015	T41	Yealink neutral version	36.80.23.1	Transplant customized configurations for the UK.
11/6/2015	T42	Yealink neutral version	29.80.23.1	Transplant customized configurations for the UK.
5/5/2016	T40/41/42	xx.80.23.xx	xx.80.0.108	<ol style="list-style-type: none"> 1. Fixed the voice quality issue. 2. Fixed problem about re-registering after de-register 3. support: BSFT R20 call recording pause feature (with yuk bsft special cfg) 4. Disable Rport by default. 5. Fix issue: phone send busy here on 3rd call. 6. Fixed the issue where a Call cut off with hold caused by c line 0.0.0.0. 7. Fix 802.1x EAP-FAST issue For T40 <p>Move customization to neutral version. All changes can be provisioned</p>
8/10/2016	T40/41/42	xx.80.0.108	xx.80.0.136	<ol style="list-style-type: none"> 1. Fixed the caller ID display issue 2. Confirmed that the Port issue is not on this version. 3. Confirmed that the failover issue is not on this version 4. Fixed the failover issue reported by DRD.

Yealink UK T46G – V80 Change log.

Release date	Model	Firmware Version		Changelog
		Form	To	
11/12/2015	T46	Yealink neutral version	28.80.23.1	Transplant customized configurations for the UK
5/5/2016	T46	28.80.23.1/101	28.80.0.108	<ol style="list-style-type: none"> 1. fixed issue: Registration issues when implementing - sip.trust_ctrl = 1 2. fix issue: Call cut off with hold caused by c line 0.0.0.0. 3. support: BSFT R20 call recording pause feature (with yuk bsft special cfg) 4. Fixed issue: Failover issue. 5. Fixed issue: phone send busy here on 3rd call 6. Disable Rport by default. 7. Fixed the voice quality issue. <p>Moved customization to neutral version. All changes can be provisioned</p>
8/10/2016	T46	28.80.0.108	28.80.0.136	<ol style="list-style-type: none"> 1. Fixed the caller ID display issue. 2. Confirmed that the Port issue is not on this version. 3. Confirmed that the failover issue is not on this version. 4. Fixed the failover issue.

Yealink UK T48G – V80 Change log.

Release date	Model	Firmware Version		Changelog
		Form	To	
11/12/2015	T48	Yealink neutral version	35.80.23.1	Transplant customized configurations for the UK.
5/5/2016	T48	35.80.23.xx	35.80.0.108	<ul style="list-style-type: none"> 1. support: BSFT R20 call recording pause feature (with yuk bsft special cfg) 2. Disable Rport by default 3. Fixed the voice quality issue <p>Moved customization to neutral version. All changes can be provisioned</p>
8/10/2016	T48	35.80.0.108	35.80.0.136	<ul style="list-style-type: none"> 1. Fixed the caller ID display issue 2. Confirmed that the Port issue is not on this version. 3. Confirmed that the failover issue is not on this version. 4. Fixed the failover issue.

Yealink UK (new)T2X – V80 Change log.

Release date	Model	Firmware Version		Changelog
		Form	To	
3/11/2015	T21(P) E2	Yealink neutral version	52.80.23.1	Transplant customized versions of T21 to T21 E2.
4/28/2015	T23	Yealink neutral version	44.80.23.1	Transplant customized versions of T22 to T23
4/28/2015	T27	Yealink neutral version	45.80.23.1	Transplant customized versions of T26 to T27
4/28/2015	T29	Yealink neutral version	46.80.23.1	Transplant customized versions of T28 to T29.
8/21/2015	T23	44.80.23.1	44.80.23.2	Fix the power LED flashing issue
8/28/2015	T19(P) E2	Yealink neutral version	53.80.23.1	Transplant customized versions of T19toT19 E2.
10/26/2015	T23	44.80.23.2	44.80.23.3	Develop for prevent the rollback to older FW, because rollback to older FW will cause cannot find IP issue.
11/6/2015	T27	45.80.23.1	45.80.23.2	Add auto-p code
11/12/2015	T23	44.80.23.3	44.80.23.4	Remove "Prevent the rollback to older FW"
5/5/2016	T29	46.80.xx.xx	46.80.0.108	<p>1.fixed issue with Registration when implementing - sip.trust_ctrl = 1</p> <p>2.fixed issue: Call cut off with hold caused by c line 0.0.0.0</p> <p>3. support: BSFT R20 call recording pause feature (with yuk bsft special cfg)</p> <p>4. Fix issue: Failover issue</p> <p>5. Fix issue: phone send busy here on 3rd call</p> <p>6. Disable Rport by default</p> <p>7. Fixed the voice quality issue</p>

				Move customization to neutral version. All changes can be provisioned
5/5/2016	T27/T23/T1 9P E2	xx.80.xx.xx	xx.80.0.108/ T21PE2-52.80.0.1 24	<ol style="list-style-type: none"> 1. Fixed the voice quality issue 2. Support: BSFT R20 call recording pause feature (with yuk bsft special cfg) 3. Fix 802.1x EAP-FAST issue 4. Disable Rport by default 5. Fix issue: phone send busy here on 3rd call <p>Move customization to neutral version. All changes can be provisioned</p>
8/10/2016	New T2x	xx.80.0.108/52.80.0.1 24	xx.80.0.136	<ol style="list-style-type: none"> 1. Fixed the caller ID display issue 2. Confirmed that the Port issue is not on this version 3. Confirmed that the failover issue is not on this version 4. Fixed the failover issue