

**Yealink UK T3x - V70 Change log.**

Release date	Model	Firmware Version		Change log	Note
		Form	To		
02/11/2012	T32 T38	32.0.23.15 38.0.23.23	3x.70.23.1	Based on 3x.70.0.116, added all custom setting in 32.0.23.15/38.0.23.23 into 3x.70.23.1, please refer to Yealink T3X-V70 Release Notes V1.4.docx	
08/11/2012	T32 T38	3x.70.23.1	3x.70.23.2	Fixed the issue that RPS is disabled by default	
13/11/2012	T32 T38	3x.70.23.2	3x.70.23.3	Fixed the issue that RPS AutoP fails when username and password are needed in HTTP server	
30/11/2012	T32 T38	3x.70.23.3	3x.70.23.4	Fixed the issue that ring-back tone can't be heard when VPN is open	
22/02/2013	T32 T38	3x.70.23.4	3x.70.23.5	Fixed the issue that distinctive ring is not working in Avaya	
27/02/2013	T32 T38	3x.70.23.5	3x.70.23.6	Fixed the transfer failure issue in Zultys PBX	
11/03/2013	T32 T38	3x.70.23.6	3x.70.23.7	Added RTCP-XR feature	
02/04/2013	T32 T38	3x.70.23.7	3x.70.23.8	Based on 32.70.0.130/38.70.0.125, added all custom setting in 3x.70.23.7 into 3x.70.23.8.	
11/04/2013	T32 T38	3x.70.23.8	3x.70.23.9	Fixed the issue that when upgrade the AutoP URL is defaulted back to the default setting.	
29/06/2013	T32 T38	3x.70.23.9	3x.70.23.10	Fixed the issue that the phone stays in Network Setup page for more than 3 minutes when upgrading from V61 to V70	

16/05/2014	T32 T38	3x.70.23.10	3x.70.23.11	Fixed BLF list issue that it will warn "Address Incomplete" when the value of BLF list is incomplete.	
18/08/2014	T32 T38	3x.70.23.11	3x.70.23.12	Fixed the CRLF and XSS security breach.	
05/11/2014	T32 T38	3x.70.23.12	3x.70.23.13	Fixed the issue of LDAP name will not refresh during transfer.	