

Yealink UK VP530 - V70 Change log.

Release date	Model	Firmware Version		Change log	Note
		Form	To		
24/07/2012	VP530	N/A	23.70.23.1	1. RPS enabled 2. Video Out enabled 3. Fixed DHCP Option 66 autop issue	
03/08/2012	VP530	23.70.23.1	23.70.23.2	Fixed the call quality issue	
16/04/2013	VP530	23.70.23.2	23.70.23.3	Transfer failed issue.	
16/01/2014	VP530	23.70.23.3	23.70.23.4	Disable the request of Content-Type: application / media_control+xml	