

Yealink UK W52 - Change log.

Release date	Model	Firmware Version		Change log	Note
		Form	To		
28/09/2013	W52	25.30.0.48	25.70.23.49	<ul style="list-style-type: none"> 1. RPS enabled. 2. Time Zone: 0, United Kingdom (London). 3. Auto Provisioning server: Http://prov.yealink.co.uk/1/ap/ 4. Disabled display Missed Call sign on LCD. 5. Optimized Battery Overheating issue after charging. 	Dial tone of Great Britain is OK
18/11/2013	W52	25.30.0.54	25.30.23.54	Add a PIN code for registering.	
20/12/2014	W52	25.40.0.1	25.40.23.1	Updated based on the OTA neutral FW	
15/11/2013	W52	25.40.23.1	25.40.23.2	<ul style="list-style-type: none"> 1. Fixed Click to dial doesn't work issue. 2. Added SCA feature. Please update the handset at the same time. 	
17/02/2014	W52	25.40.23.2	25.40.23.3	1.Fixed RPS failed with iHUB server issue.	
22/05/2014	W52	25.40.23.3	25.50.23.2	<ul style="list-style-type: none"> 1. Updated the firmware from V40 to V50 <p>SSL certificate based on MAC code added during manufacture.</p> <p>Please note this Base firmware should be used in conjunction with Handset firmware 26.50.0.23</p>	
23/07/2014	W52	25.50.23.2	25.50.23.3	Fixed the issue that the phone can't receive a call when INVITE package is too big.	