

**Yealink UK T4x - V71 Change log.**

Release date	Model	Firmware Version		Change log	Note
		Form	To		
18/11/2013	T41	36.71.0.55	36.71.23.2	1. RPS enabled. 2. Time Zone: 0,United Kingdom (London). 3. Auto Provisioning server: <a href="http://prov.yealink.co.uk/1/ap/">http://prov.yealink.co.uk/1/ap/</a> 4. Default tone: great britain. 5. auto_provision.aes_key_in_file = 1 6. auto_provision.update_file_mode = 0 7. Only Accept Trusted Certificates enabled 8. Added GlobalSigns Root Certificate: GlobalSign_Root_CA_R1.cer	
11/12/2013	T41	36.71.23.2	36.71.23.3	Take effect after reset: 2. Time Zone: 0,United Kingdom (London). 3. Auto Provisioning server: <a href="http://prov.yealink.co.uk/1/ap/">http://prov.yealink.co.uk/1/ap/</a> 4. Default tone: great britain. 7. Only Accept Trusted Certificates enabled  Take effect after upgrade: 5. auto_provision.aes_key_in_file = 1 6. auto_provision.update_file_mode = 0.	
15/10/2013	T42	29.71.0.101	29.71.23.1	Auto provisioning URL: <a href="http://prov.yealink.co.uk/1/ap/">http://prov.yealink.co.uk/1/ap/</a> Default time zone: 0, United Kingdom (London) BSFT active: enabled	Confirmed RPS works
18/11/2013	T42	29.71.23.1	29.71.23.2	1. RPS enabled. 2. Time Zone: 0,United Kingdom (London). 3. Auto Provisioning server: <a href="http://prov.yealink.co.uk/1/ap/">http://prov.yealink.co.uk/1/ap/</a> 4. Default tone: great britain. 5. auto_provision.aes_key_in_file = 1 6. auto_provision.update_file_mode = 0 7. Only Accept Trusted Certificates enabled 8. Added GlobalSigns Root Certificate: GlobalSign_Root_CA_R1.cer 9.Disabled BSFT active. 10.SIP server type: default.	

11/12/2013	T42	29.71.23.2	29.71.23.3	<p>Take effect after reset:</p> <p>2. Time Zone: 0,United Kingdom (London).</p> <p>3. Auto Provisioning server: http://prov.yealink.co.uk/1/ap/</p> <p>4. Default tone: great britain.</p> <p>7. Only Accept Trusted Certificates enabled</p> <p>Take effect after upgrade:</p> <p>5. auto_provision.aes_key_in_file = 1.</p> <p>6. auto_provision.update_file_mode = 0.</p>	
15/10/2013	T46	28.71.0.171	28.71.23.1	<p>Auto provisioning URL: http://prov.yealink.co.uk/1/ap/</p> <p>Default time zone: 0, United Kingdom (London)</p> <p>BSFT active: enabled</p>	Confirmed RPS worked.
13/11/2013	T46	28.71.23.1	28.71.23.2	<p>1. RPS enabled.</p> <p>2. Time Zone: 0, United Kingdom (London).</p> <p>3. Auto Provisioning server: http://prov.yealink.co.uk/1/ap/</p> <p>4. Default tone: great britain.</p> <p>5. auto_provision.aes_key_in_file = 1</p> <p>6. auto_provision.update_file_mode = 0</p> <p>7. Only Accept Trusted Certificates enabled</p> <p>8. Added GlobalSigns Root Certificate: GlobalSign_Root_CA_R1.cer</p>	
16/11/2013	T46	28.71.23.2	28.71.23.3	<p>Disabled BSFT active.</p> <p>SIP server type: default.</p>	
11/12/2013	T46	28.71.23.3	28.71.23.4	<p>Take effect after reset:</p> <p>2. Time Zone: 0, United Kingdom (London).</p> <p>3. Auto Provisioning server: http://prov.yealink.co.uk/1/ap/</p> <p>4. Default tone: great britain.</p> <p>7. Only Accept Trusted Certificates enabled</p> <p>Take effect after upgrade:</p> <p>5. auto_provision.aes_key_in_file = 1.</p> <p>6. auto_provision.update_file_mode = 0.</p>	