

Yealink UK T2x - V70 Change log.

Release date	Model	Firmware Version		Changelog
		Form	To	
19/02/2013	T20/T22/T26/T28	x.61.23.17	x.70.23.1	1. First part: Based on x.70.0.141, added all custom setting in x.61.23.17 into x.70.23.1, please refer to "Yealink SIP Phone Release Note of Version 70.docxf" 2.Second part: Add the right ACD feature in V61 into x.70.23.1 in advance.
27/02/2013	T20/T22/T26/T28	x.70.23.1	x.70.23.2	Fixed the transfer failure issue in Zultys PBX
11/03/2013	T20/T22/T26/T28	x.70.23.2	x.70.23.3	Added RTCP-XR feature
11/04/2013	T20/T22/T26/T28	x.70.23.3	x.70.23.4	Fixed the Broadsoft CLIP not showing A-Party on transfer issue
20/04/2013	T20/T22/T26/T28	x.70.23.4	x.70.23.5	Fix the Only Accept Trusted Certificates option issue
29/04/2013	T20/T22/T26/T28	x.70.23.5	x.70.23.6	Disable the feature that sets BLF List manually
20/06/2013	T20/T22/T26/T28	x.70.23.6	x.70.23.7	Fixed discontinuous ring issue when Plantronics headset work with EHS
28/06/2013	T20/T22/T26/T28	x.70.23.7	x.70.23.8	Fixed no RPS when power on issue and AutoP upgrade / downgrade issue.
18/07/2013	T22/T26/T28	x.70.23.8	x.70.23.9	Fixed the search issue about Remote Phonebook
29/07/2013	T22/T26/T28	x.70.23.9	x.70.23.10	Fixed the issue that phone will not to match in LDAP server after CID updates